

ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE REGULATORY CONTACT RECORD

Date/Time: November 9, 1999 / approximately 10:50 a.m.

Site Contact(s): Bob Cathel **Phone:** 966-6880
Carolyn Hicks **Phone:** 966-5773

Regulatory Contact: Edd Kray **Phone:** 966-2115

Agency: Colorado Department of Public Health & Environment

Purpose of Contact: Discuss removal of piping between B777 and B779 relative to B776/777 DOP.

Discussion:

The piping is an out of service machine coolant line that runs from B779 through B777 to B774. This piping is not part of any of the Sets identified in the B776/777 DOP or part of any interim status or permitted unit. B776 personnel will be cutting the piping just inside B777 and removing approximately 20' of piping that is exterior to B777. The piping will be size reduced per procedure in B776/777. An ultrasonic inspection of the piping indicated that the pipe is empty but may contain very small amounts of residual liquid or debris. Any liquid that may be collected from this operation will be containerized and characterized as appropriate. Edd was provided with a copy of the IWCP (T0101755) for performance of this work. Edd concurred with this approach and the approval to proceed with this operation has been communicated with B776 project personnel.

Contact Record Prepared By: Bob Cathel, RMRS Environmental Compliance

Distribution:

R. DiSalvo, RFFO
S. MacLeod, RFFO
G. Schuetz, RFFO
E. Kray, CDPHE
T. Hopkins, RMRS
B. McPherson, RMRS
L. Tyler, RMRS
T. Dieter, RMRS
M. Kriz, RMRS

R. Leitner, Proctors Enterprise
K. Myers, Proctors Enterprise
R. Walker, K-H
S. Rose, K-H
D. Shelton, K-H
F. Phillips, K-H
K. North, K-H



Contact Record 11/9/99